




TABLE I

ELECTRICAL CONNECTION
SIGNAL OUT
CURRENT TORQUE
-13 TO -28 VDC
+13 TO +28 VDC
NC
TEMPERATURE SENSOR OUT
VOLTAGE SELF TEST
SIGNAL AND POWER RETURN
- REGULATED OUTPUT
+ REGULATED OUTPUT

THIS DOCUMENT IS AN UNPUBLISHED WORK. COPYRIGHT 1979, 1984,
HONEYWELL INTERNATIONAL INC. ALL RIGHTS RESERVED.

OUTLINE, ACCELEROMETER MODEL QA 2000

HONEYWELL INTERNATIONAL INC.
REDMOND, VA 00673-0701

PART NO. 979-2000-001, -002, -003

EXP-005